

7 Twin Circle Drive, Arlington, MA 02474

## Memorandum

**To:** Board of Selectmen, Arlington, Mass **From:** Transportation Advisory Committee

Subject: Revisit Dickson/Wheeler Recommendation

Reference: TAC Memo to Board on 5/21/06

Date: January 8, 2007

On May 21 we recommended and the Board voted stop signs on the Dickson approaches to Wheeler based upon traffic data and field observations. Experience since then has since shown that the curvature of the southeast corner of that intersection is so large that the corner is ill defined and the stop sign on that corner is not effective.

The TAC voted unanimously at our December 12 meeting to recommend modifying the stop sign locations to be on Wheeler rather than Dickson. The corners on Wheller are well defined and the placement can be effective.

## Recommendation:

Remove existing stop signs on Dickson at Wheeler and replace on Wheeler Lane at Dickson.

Respectfully submitted,

Edward Starr Chair of Transportation Advisory Committee